

Form Information


Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 3, 2018 2:22:40 PM MST
Server Receive Date:	Jan 3, 2018 2:22:44 PM MST
Reference Number:	20180103-1871349940
Location:	101-1079 S Skylane Dr, Durango, CO 81303, USA Jan 3, 2018 2:22:14 PM MST [View Map]

Information

Name	reclamationtablet
Date	Jan 2, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NW Team
Well Name	HOTTER, JOE GAS UNIT 2
API Number	50670870800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Completed work description

Cut and removed weed debris