

Form Information

| | |
|----------------------|--|
| Form Name: | Compliance Follow Up Form |
| Submitter Name: | Reclamation Tablet (reclamationtablet) |
| Submission Date: | Jan 4, 2018 11:24:59 AM MST |
| Server Receive Date: | Jan 4, 2018 11:25:06 AM MST |
| Reference Number: | 20180104-1871389399 |
| Location: | 1357 Co Rd 303, Durango, CO 81303, USA Jan 4, 2018 11:24:55 AM MST [View Map] |

Information

| | |
|---|----------------------|
| Name | reclamationtablet |
| Date | Jan 4, 2018 |
| Optional - Type Part of the Run Number or Lateral to Filter for Next Question | NW |
| Well Name | MCMAHAN GAS UNIT 1 |
| API Number | 50670695200 |
| Select State | Colorado |
| Work type | COGCC Inspection AR |
| Action Complete | Clean Up Weed Debris |
| Picture North to South | |



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

removed musk thistle and mowed weed skeletons