



Form Information


Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 4, 2018 12:33:24 PM MST
Server Receive Date:	Jan 4, 2018 12:33:32 PM MST
Reference Number:	20180104-1871393800
Location:	1512-1926 Co Rd 301, Durango, CO 81303, USA Jan 4, 2018 12:32:45 PM MST [View Map]

Information

Name	reclamationtablet
Date	Jan 4, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NW
Well Name	SIMON LAND & CATTLE 15U-2R 2
API Number	50670838800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

Notes

removed weed skeletons and rosettes

could not access behind fence where yellow trailer is