



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 4, 2018 2:24:45 PM MST
Server Receive Date:	Jan 4, 2018 2:24:52 PM MST
Reference Number:	20180104-1871404187
Location:	131 Moonridge Dr, Durango, CO 81303, USA Jan 4, 2018 2:24:19 PM MST [View Map]

Information

Name	reclamationtablet
Date	Jan 4, 2018
Optional - Type Part of the Run Number or Lateral to Filter for Next Question	NW
Well Name	DUSTIN GAS UNIT 09-01 1
API Number	50670665100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West




Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

mowed and removed musk thistle skeletons and rosettes