

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/09/2018

Submitted Date:

01/09/2018

Document Number:

677400342**FIELD INSPECTION FORM**
 Loc ID 452525 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS
Ellsworth, Stuart		stuart.ellsworth@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452488	WELL	DG	01/06/2018		123-45621	Shufly State Y34-714	DG

**General Comment:**

**Location****Lease Road:**

Type	Main		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	ok, in Company man office	Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 452488 Type: WELL API Number: 123-45621 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: H&P517 Pusher/Rig Manager: John Drahota  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: YES  
 Multi-Well: NO Disposal Location: Waste Management

Comment: \_\_\_\_\_

Corrective Action:

**BMP'S IN ORDER AROUND LOCATION, ALL DRILLING MUD AND GEL IN CONTAINMENTS, ALL GOOD OIL AND WASTE OIL ON CONTAINMENTS, PIPE ON RACKS, NO TRASH AROUND LOCATION, THEY ARE IN THE PROCESS OF DRILLING OUT STUMP PLUG, INSPECTION LOOKED GOOD**

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<b>DRILLING RIG INSPECTION</b>	montoyaj	01/09/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
677400343	RIG AND BMP'S	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4345274">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4345274</a>