

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/11/2018

Submitted Date:

01/11/2018

Document Number:

679903754

FIELD INSPECTION FORM

Loc ID 321809 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: 1700 N WATERFRONT PKWY B#1200
City: WICHITA State: KS Zip: 67206-

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Smalley, Carl	719-767-8805	csmalley@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208086	WELL	PR	12/31/1991	OW	017-07021	NW ARAPAHOE UT (NWAU) 34	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:

	Type Access		
comment:	Elevated gravel road through farm ground		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

		#		corrective date
Type: Pump Jack		# 1		
Comment:	American 228			
Corrective Action:			Date:	
Type: Deadman # & Marked		# 4		
Comment:				
Corrective Action:			Date:	
Type: Ancillary equipment		# 2		
Comment:	Electric panel			
Corrective Action:			Date:	
Type: Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			

Corrective Action:

Date:

Inspected Facilities

Facility ID: 208086 Type: WELL API Number: 017-07021 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(NWAU 29, 30, 31, 32, 34, 35\) 1500' NE @ 38.857600/-102.153220](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT