

Tonder 17-1 (PA17)  
Api# 05-017-145-15194  
Inspection # 689700862



Location photo from north of location.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Tonder 17-1 (PA17)  
Api# 05-017-145-15194  
Inspection # 689700862



Location photo from north of location.

Tonder 17-1 (PA17)  
Api# 05-017-145-15194  
Inspection # 689700862



Airs id sticker on condensate tank needs replaced.