




## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jan 11, 2018 9:34:18 AM MST
Server Receive Date:	Jan 12, 2018 8:30:01 AM MST
Reference Number:	20180111-1871688927
Location:	3303 N 1st St, Bloomfield, NM 87413, United States Jan 11, 2018 9:33:11 AM MST [ <a href="#">View Map</a> ]

## Information

Name	celkins@gobrainstorm.net
Date	Jan 9, 2018
Well Name	FEINBERG GAS UNIT C 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down

## Picture North to South



## Picture South to North



## Picture East to West



Picture West to East



Additional photos

