

Inspection Photos

01/11/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 318670

Inspection Doc. Number: 682503070

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the east end of the location, facing west. Previous inspections required operator to remove pipe risers from location. Photo shows pipe riser equipment remains on location.