

# Inspection Photos

01/11/2018

Operator: NOBLE ENERGY INC - 100322

Location ID: 329551

Inspection Doc. Number: 682503076

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the south end of the well location, facing north. Photo shows vegetation over the well location has not achieved a uniform cover, and does not appear to be progressing towards an 80% desirable perennial cover to that of the reference. Vegetation observed on well predominantly undesirable weedy plant species. Photo also shows no reclamation activities appear to have been conducted per the corrective actions.



**Photo 2:** Photo taken from the well location, facing east. Photo shows water movement patterns and erosion degradation beginning to form. Site does not appear to be stabilized. Photo also shows no reclamation activities appear to have been conducted per the corrective action.



Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 329551



**Photo 3:** Photo taken from the adjacent reference area. Reference area is an irrigated hay meadow composed predominantly of perennial grass.



**Photo 4:** Photo taken from former battery location. Photo shows meter shed equipment has not been removed per corrective actions.