

Photo#1:

View North from Main Road, over Access Road & into Location.



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Mesa Loc#324396

Photo#2:
View Northwest over Location from Entry.



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Mesa Loc#324396

Photo#3:

View to East over Pad; Position of PA Well on Location indicated by Stake.



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Mesa Loc#324396

Photo#4:

View to Northeast along East Fill Slope.



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Mesa Loc#324396

Photo#5:
Pad remains Graveled



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus Mesa Loc#324396