

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/29/2017

Submitted Date:

01/12/2018

Document Number:

680102576**FIELD INSPECTION FORM**

Loc ID 324396	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	Status Summary:
2A Doc Num: _____			<input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b>  OGCC Operator Number: <u>10456</u>  Name of Operator: <u>CAERUS PICEANCE LLC</u>  Address: <u>1001 17TH STREET #1600</u>  City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>			<b>Findings:</b>  <u>2</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442910	WELL	XX	08/21/2015	LO	045-22936	Puckett 43B-12	RI
442911	WELL	XX	08/21/2015	LO	045-22937	Puckett 23C-6	RI
442912	WELL	XX	08/21/2015	LO	045-22938	Puckett 24C-6	RI
442913	WELL	XX	08/21/2015	LO	045-22939	Puckett 32B-6	RI
442914	WELL	XX	08/21/2015	LO	045-22940	Puckett 13B-6	RI
442915	WELL	XX	08/21/2015	LO	045-22941	Puckett 43A-12	RI
442916	WELL	XX	08/21/2015	LO	045-22942	Puckett 14A-6	RI
442917	WELL	XX	08/21/2015	LO	045-22943	Puckett 14C-6	RI
442918	WELL	XX	08/21/2015	LO	045-22944	Puckett 23A-6	RI
442919	WELL	XX	08/21/2015	LO	045-22945	Puckett 14D-6	RI
442920	WELL	XX	08/21/2015	LO	045-22946	Puckett 13D-6	RI
442921	WELL	XX	08/21/2015	LO	045-22947	Puckett 32C-6	RI
442922	WELL	XX	08/21/2015	LO	045-22948	Puckett 23D-6	RI
442923	WELL	XX	08/21/2015	LO	045-22949	Puckett 42D-12	RI
442924	WELL	XX	08/21/2015	LO	045-22950	Puckett 33B-6	RI
442925	WELL	XX	08/21/2015	LO	045-22951	Puckett 42C-12	RI
442926	WELL	XX	08/21/2015	LO	045-22952	Puckett 24A-6	RI
442927	WELL	XX	08/21/2015	LO	045-22953	Puckett 33D-6	RI
442928	WELL	XX	08/21/2015	LO	045-22954	Puckett 13A-6	RI
442929	WELL	XX	08/21/2015	LO	045-22955	Puckett 32D-6	RI

**General Comment:**

This is a Final Reclamation Inspection for Location#324396 and Twenty Four XX Wells listed in Inspected Facilities, above. 2A to Expand Location (Date planned to commence construction: 10/01/2015) was Approved 8/21/15; this Construction has Not Occurred; APDs for the XX Wells Expired in 2017. Location Fails Final Reclamation as Site has not been Reclaimed. Operator of Record for PA Well on Site is Other than Caerus. Operator of PA Well will also Receive Failing Final Reclamation Inspection. CAs & CA Dates (Except for Abandoning Permits) will be the same in both Inspections.

Site appears to have been Built in late 2005; before Spud of Well API#045-13353 on 10/2/05.

Inspected Facilities				
Facility ID: <u>442910</u>	Type: <u>WELL</u>	API Number: <u>045-22936</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442911</u>	Type: <u>WELL</u>	API Number: <u>045-22937</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442912</u>	Type: <u>WELL</u>	API Number: <u>045-22938</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442913</u>	Type: <u>WELL</u>	API Number: <u>045-22939</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442914</u>	Type: <u>WELL</u>	API Number: <u>045-22940</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442915</u>	Type: <u>WELL</u>	API Number: <u>045-22941</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442916</u>	Type: <u>WELL</u>	API Number: <u>045-22942</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442917</u>	Type: <u>WELL</u>	API Number: <u>045-22943</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442918</u>	Type: <u>WELL</u>	API Number: <u>045-22944</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442919</u>	Type: <u>WELL</u>	API Number: <u>045-22945</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442920</u>	Type: <u>WELL</u>	API Number: <u>045-22946</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442921</u>	Type: <u>WELL</u>	API Number: <u>045-22947</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442922</u>	Type: <u>WELL</u>	API Number: <u>045-22948</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442923</u>	Type: <u>WELL</u>	API Number: <u>045-22949</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442924</u>	Type: <u>WELL</u>	API Number: <u>045-22950</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442925</u>	Type: <u>WELL</u>	API Number: <u>045-22951</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442926</u>	Type: <u>WELL</u>	API Number: <u>045-22952</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442927</u>	Type: <u>WELL</u>	API Number: <u>045-22953</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>
Facility ID: <u>442928</u>	Type: <u>WELL</u>	API Number: <u>045-22954</u>	Status: <u>XX</u>	Insp. Status: <u>RI</u>

Facility ID:	442929	Type:	WELL	API Number:	045-22955	Status:	XX	Insp. Status:	RI
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed Pass No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded **Fail** Contoured **Fail** Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed **Fail** Locations, facilities, roads, recontoured **Fail**

Compaction alleviation **Fail** Dust and erosion control **Fail**

Non cropland: Revegetated 80% **Fail** Cropland: perennial forage \_\_\_\_\_

Weeds present Pass Subsidence Pass

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: Location does not meet Reclamation Regulations; Site has not been Reclaimed. Historical Aerial imagery does not indicate that Site was Reclaimed One Year after Plugging of Well (7/7/06). 2A to Expand Location (Date planned to commence construction: 10/01/2015) was Approved 8/21/15; this Construction has Not Occurred; APDs for the XX Wells Expired in 2017.

Inspector Name: Colby, Lou

Corrective Action:	There are two CAs in this Section. CA#1) Abandon Permits on XX Wells with Expired Permits by 2/16/18. CA#2) Perform Final Reclamation per COGCC 1004 Rules; Reclamation Activities to be complete by June 15, 2018.	Date	02/16/2018
Overall Final Reclamation	Fail	Well Release on Active Location	<input type="checkbox"/>
		Multi-Well Location	<input type="checkbox"/>

### **Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680102581	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4350034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4350034</a>