

Inspection Photos
Location Name: J P Weise 1
API: 05-081-05289



Photo 1. Overview of location taken at entrance facing southeast.

Inspection Photos
Location Name: J P Weise 1
API: 05-081-05289



Photo 2. Riser not marked or LOTO.



Photo 3. Pit.