

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2018

Submitted Date:

01/16/2018

Document Number:

680302885**FIELD INSPECTION FORM**Loc ID 420857 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 200149Name of Operator: ATLAS RESOURCES LLC DBA ATLAS ROCKIES LLCAddress: 3500 MASSILLON ROAD #100City: UNIONTOWN State: OH Zip: 44685**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**4 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Walker, Chris	(817)439-4561	cwalker@atlasenergy.com	All Inspections
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420868	WELL	PR	03/13/2012	GW	095-06298	Lindstrom 944-35-12	SI

General Comment:

Routine Site Inspection FIR

Any/all previous CA citations that remain unresolved are in force. Contact: COGCC Engineering Supervisor (Diana Burn) for directives. COGCC Enforcement Supervisor (Jeremy Ferrin) for directives. COGCC Quality Assurance Supervisor (Mike Leonard) for directives.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Install signage to comply with Rule 210 series.		
Corrective Action:	Install sign to comply with Rule 210 series.		Date: 02/10/2018

Emergency Contact Number:

Comment:			
Corrective Action:	Install signage to comply with Rule 210 series		Date: 02/10/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	420868	Type:	WELL	API Number:	095-06298	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Well is SI/TA status. Listed as PR. Last production report June 2017. Contact COGCC Engineering Supervisor (Diana Burn) for directives.									
Corrective Action: Update well status. Update production reporting. Install valid signage. Date: 02/10/2018									