

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2018

Submitted Date:

01/16/2018

Document Number:

680302896**FIELD INSPECTION FORM**
 Loc ID 314076 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 200149Name of Operator: ATLAS RESOURCES LLC DBA ATLAS ROCKIES LLCAddress: 3500 MASSILLON ROAD #100City: UNIONTOWN State: OH Zip: 44685**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Walker, Chris	(817)439-4561	cwalker@atlasenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293598	WELL	PR	02/01/2012	GW	095-06167	MURRAY 943-34-21	SI

**General Comment:**

Routine Site Inspection FIR  
 Contact COGCC Engineering Supervisor (Diana Burn) for directives.  
 Enforcement Supervisor (Jeremy Ferrin) for directives.  
 Quality Assurance Supervisor (Mike Leonard) for directives.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:	Install sign to comply with Rule 210 series.	Date:	02/10/2018

**Emergency Contact Number:**

Comment:		
Corrective Action:	Install sign to comply with Rule 210 series.	Date: 02/10/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 293598 Type: WELL API Number: 095-06167 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well is listed as PR. Well is SI/TA status. Last production reporting June 2017Corrective Action: Update well status. Update production reports. Install valid signage.Date: 02/10/2018