

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/16/2018

Submitted Date:

01/16/2018

Document Number:

689700884**FIELD INSPECTION FORM**

Loc ID 335503	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 21 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:			
OGCC Operator Number: <u>96850</u>			
Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u>			
Address: <u>PO BOX 370</u>			
City: <u>PARACHUTE</u>	State: <u>CO</u>	Zip: <u>81635</u>	

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298949	WELL	PR	09/30/2009	GW	045-17487	BUXTON RWF 313-30	PR
298950	WELL	PR	12/11/2009	GW	045-17488	BUXTON RWF 13-30	PR
298951	WELL	PR	09/30/2009	GW	045-17489	BUXTON RWF 413-30	PR
298952	WELL	PR	01/11/2010	GW	045-17490	BUXTON RWF 513-30	PR
298953	WELL	PR	01/11/2010	GW	045-17491	BUXTON RWF 14-30	PR
298954	WELL	PR	08/11/2009	GW	045-17492	BUXTON RWF 314-30	PR
298955	WELL	PR	03/29/2010	GW	045-17493	BUXTON RWF 514-30	PR
298956	WELL	PR	10/14/2008	GW	045-17494	BUXTON RWF 323-30	PR
298957	WELL	PR	01/11/2010	GW	045-17495	BUXTON RWF 423-30	PR
298958	WELL	PR	08/30/2009	GW	045-17496	BUXTON RWF 523-30	PR
298959	WELL	PR	08/31/2009	GW	045-17497	BUXTON RWF 24-30	PR
298960	WELL	PR	06/16/2009	GW	045-17498	BUXTON RWF 324-30	PR
298961	WELL	PR	06/16/2009	GW	045-17499	BUXTON RWF 424-30	PR
298962	WELL	PR	03/29/2010	GW	045-17500	BUXTON RWF 333-30	PR
298963	WELL	PR	09/30/2009	GW	045-17501	BUXTON RWF 33-30	PR
298964	WELL	PR	01/11/2010	GW	045-17502	BUXTON RWF 432-30	PR
299068	WELL	PR	01/11/2010	GW	045-17548	BUXTON RWF 23-30	PR
299069	WELL	PR	06/30/2009	GW	045-17549	BUXTON RWF 524-30	PR
299070	WELL	PR	04/06/2012	GW	045-17550	BUXTON RWF 522-30	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Piping laying on edge of location.		
Corrective Action:	Comply with Rule 603.f .	Date:	02/17/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Type	TANK BATTERY			
Comment:				
Corrective Action:			Date:	

Equipment:			corrective date
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 19		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	Chemical containers at wells.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	298949	Type:	WELL	API Number:	045-17487	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298950	Type:	WELL	API Number:	045-17488	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298951	Type:	WELL	API Number:	045-17489	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298952	Type:	WELL	API Number:	045-17490	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298953	Type:	WELL	API Number:	045-17491	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:						Date:			
Facility ID:	298954	Type:	WELL	API Number:	045-17492	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298955	Type:	WELL	API Number:	045-17493	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298956	Type:	WELL	API Number:	045-17494	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	298957	Type:	WELL	API Number:	045-17495	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298958	Type:	WELL	API Number:	045-17496	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298959	Type:	WELL	API Number:	045-17497	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298960	Type:	WELL	API Number:	045-17498	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298961	Type:	WELL	API Number:	045-17499	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298962	Type:	WELL	API Number:	045-17500	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298963	Type:	WELL	API Number:	045-17501	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	298964	Type:	WELL	API Number:	045-17502	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	299068	Type:	WELL	API Number:	045-17548	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	299069	Type:	WELL	API Number:	045-17549	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	299070	Type:	WELL	API Number:	045-17550	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689700885	RFW 23-30 pad photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4352766