

Inspection Photos

Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Entrance Sign at cattle guard



Entrance Sign to Land Treatment Facility.



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Culvert and storm water controls



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Gate to entrance secured with lock



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Looking south from NE corner of Facility



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Looking west from NE corner of Facility



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Four piles of untreated material in Treatment Pod #4



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Looking west from SW corner of the Facility



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Trash/Debris in Treatment Pod #3



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Trash/Debris in Treatment Pod #3



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Looking northeast across Facility from SW corner of Facility



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Looking northeast across the Land Application Area



Location Name: Walden Land Treatment Facility

Facility ID: 427373

Inspection Date: 1/16/2018



Looking northwest across the Land Application Area

