

Inspection Photos  
Location Name: Jacobs 29-1  
Location ID: 324466



Photo 1. Produced water signs have been updated.



Photo 2. Weeds have been removed from around wellhead.

Inspection Photos  
Location Name: Jacobs 29-1  
Location ID: 324466



**Photo 3. Tank photo from original inspection.**  
Chemical is present in chemical containment at the well head. No cover is in place over containment, and is open to wildlife.



**Photo 4. Tank photo from current inspection.**  
Chemical is present in chemical containment at the well head. No cover is in place over containment, and is open to wildlife.