

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 16, 2018 12:24:24 PM MST
Server Receive Date:	Jan 16, 2018 12:24:30 PM MST
Reference Number:	20180116-1871880730
Location:	600-606 Dove Ranch Rd, Bayfield, CO 81122, USA Jan 16, 2018 12:24:14 PM MST [View Map]

Information

Name	James Brown
Date	Jan 16, 2018
Well Name	DOVE, NEVA GAS UNIT A 1
API Number	50670755700
Select State	Colorado
Work type	manual weed removal
Action Complete	Compliance Inspection Actions Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

manually removed thistles