

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Jan 16, 2018 11:47:23 AM MST
Server Receive Date:	Jan 16, 2018 11:47:29 AM MST
Reference Number:	20180116-1871878280
Location:	544-614 E Oak Dr, Bayfield, CO 81122, USA Jan 16, 2018 11:47:22 AM MST [View Map]

Information

Name	James Brown
Date	Jan 16, 2018
Well Name	DOVE, NEVA GAS UNIT A 2
API Number	50670841200
Select State	Colorado
Action Complete	Compliance Inspection Actions Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

manually removed scotch thistle north of the well pad and checked the entire well pad and reclaimed area.