




## Form Information

|                      |  |
|----------------------|--|
| Form Name:           | <b>Compliance Follow Up Form</b>   |
| Submitter Name:      | Reclamation Tablet (reclamationtablet)   |
| Submission Date:     | Jan 16, 2018 9:58:49 AM MST  |
| Server Receive Date: | Jan 16, 2018 9:59:28 AM MST  |
| Reference Number:    | 20180116-1871866731  |
| Location:            | 199 Faris Rd, Durango, CO 81303, USA<br>Jan 16, 2018 9:58:40 AM MST [ <a href="#">View Map</a> ] |

## Information

|                 |  |
|-----------------|--|
| Name            | James Brown                            |
| Date            | Jan 16, 2018                           |
| Well Name       | MAYFIELD GAS UNIT A 2                  |
| API Number      | 50670893500                            |
| Select State    | Colorado                               |
| Work type       | COGCC Inspection AR                    |
| Action Complete | Compliance Inspection Actions<br>Other |

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Completed work description

manually removed scotch thistle skeletons

