

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401521036

Date Received:  
01/22/2018

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 8960  
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Brian Dodek</u>	<u>7202256653</u>	<u>bdodek@bonanzacrk.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690900009  
Inspection Date: 01/16/2018 FIR Submit Date: 01/17/2018 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Company Number: 8960  
Address: 410 17TH STREET SUITE #1400  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 450973

Location Name: Walden Land Treatment Facility Number: T7-P18 County: \_\_\_\_\_  
Qtrqr: NENE Sec: 18 Twp: 9N Range: 78W Meridian: 6  
Latitude: 40.756100 Longitude: -106.186000

FACILITY - API Number: 05-057-00 Facility ID: 427373

Facility Name: WALDEN LAND TREATMENT FACILITY Number: \_\_\_\_\_  
Qtrqr: NENE Sec: 18 Twp: 9N Range: 78W Meridian: 6  
Latitude: 40.756100 Longitude: -106.186000

CORRECTIVE ACTIONS:

**1** CA# 114081

Corrective Action: \_\_\_\_\_ Date: 02/16/2018

On January 16, 2018 COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of Bonanza Creek Energy Operating Company (BCEOC) Walden Land Treatment Facility ID: 427373. The INSP included Land Application Site 427280 and CE&P Facility 427373. The Facility is active and is being converted from a land application site to a CE&P Facility. Weather was sunny and temperature app 12 degree F with some snow cover. For the most recent Field and Environmental Field inspection report of this facility, please refer to document # 677900189. The following is a summary:

**Land Treatment Facility 427373:**

The following was observed at the CE&P Facility:

- A sign "McCallum Land Application Area" was noted at the cattle guard located approximately 0.5 mile from the entrance to the CE&P Facility.
- The gate was noted to be closed and locked.
- E & P waste materials have been incorporated in the various cells.
- Rags and plastic liner incorporated in Treatment Pod #3.
- Four app 8' dia by 5' in height pile of untreated material located in Treatment Pod #4
- Fence consists of metal "T" posts, hog wire, 2 strand of barb wire, and vinyl coated top wire. Fence app 4' in height.
- No monitoring wells were observed.
- Culvert placed near the NW corner of the Facility.
- Fire and buffer lanes constructed with brush material grubbed.
- Berms appeared adequate.

**Land Application Facility 427280:**

The following was observed at the Land Application Site: no recent cuttings have been incorporated at the location. The location appeared to be adequately bermed.

**Corrective Actions (CAs):**

Remove the sign near the cattle guard and place at the entrance of the Land Application Area.

Remove trash and debris (rags and plastic liner) and properly dispose.

Maintain berm and tracking control upon entrance into and out of Treatment Pod #4.

Provide documentation that the monitoring wells were properly abandoned in accordance to the Division of Water Resources guidance.

Response: CA COMPLETED

Date of Completion: 01/20/2018

Operator  
Comment:

- 1) The verbiage "McCallum Land Application Area" was covered on the sign. It now marks a private property area with no relation to the facility.
- 2) The trash was removed from the tilled soil.
- 3) The berm was maintained as requested.
- 4) The monitoring hole stickups were removed and casing cut below ground surface. The casing was filled with bentonite and hydrated. The monitoring hole P&A documentation is attached to this FIRR.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brian Dodek

Signed: \_\_\_\_\_

Title: Env Manager

Date: 1/22/2018 8:49:37 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401521045	Sign CA Photo
401521047	MW P&A Documentation

Total Attach: 2 Files