



Form Information


Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jan 16, 2018 3:31:59 PM MST
Server Receive Date:	Jan 22, 2018 7:33:16 AM MST
Reference Number:	20180122-1872097937
Location:	Durango, CO 81303, United States Jan 16, 2018 3:30:52 PM MST [View Map]

Information

Name	celkins@gobrainstorm.net
Date	Jan 9, 2018
Well Name	LE PLATT GAS UNIT B 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos

