

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2018

Submitted Date:

01/16/2018

Document Number:

682600444**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Kosola, Jason 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427440	WATER GATHERING SYSTEM/LINE	AC	01/25/2012		-	Pioneer Raton Basin Water Gathering 427440	EI

General Comment:

This is an environmental inspection to document status of spill of produced water. Operator reported "It is estimated at this time that 3bbls to 5bbls of produced water were spilled with no State Waters involved. The spill ran down the main road a short distance, through cattle guard were it ended in a meadow just off the road. Plans for repairs and investigation are to follow."

Inspection of spill confirms operator report. It does not appear that a large volume of fluid was spilled. Spill was primarily confined to road ditch and cattle guard.

Inspected Facilities									
Facility ID:	427440	Type:	WATER	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 5

Comment: Operator reported spill of produced water.

Corrective Action: Operator shall provide root cause of spill and prevention procedures on Form 19 Subsequent within 10 days of spill as required per Rule 906.b

Date: 01/21/2018

Reportable: YES

GPS: Lat 37.244350

Long -104.893330

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401516722	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4353239
682600445	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4353234