

Inspection Photos

API: 05-067-08158

Operator: XTO ENERGY INC

Inspection Number: 680602450

Inspection Date: 1/9/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of musk thistles (*Carduus nutans*) within the northern portion of the project area.



Photo 5. View of erosion along the eastern edge of the access road.



Photo 6. View of erosion occurring along the western portion of the access road.