

Photo#1:

View East from Main Logan Wash Road, over Location. Red line indicates Access Road path into Location..



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PDC ALs Puckett Loc#335016

Photo#2:

View South over Location from Ridge road to North of Site.



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PDC ALs Puckett Loc#335016

Photo#3:

View Southwest over Location from Ridge road to North of Site.



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PDC ALs Puckett Loc#335016

Photo#4:

Google Earth 2016 Aerial image of Location.



December 29, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: PDC ALs Puckett Loc#335016

Photo#5:

Zoomed In View; Google Earth 2016 Aerial image of Location.



December 29, 2017