

Well Name : IGE 107

API # : 067-09074



Photo 1: Wellhead sign. Previous inspection.



Photo 2: Location overview. Current inspection.

Well Name : IGE 107

API # : 067-09074



Photo 3: Fracturing sand left on location.
Previous inspection.



Photo 4: Fracturing sand on location.
Current inspection.

Well Name : IGE 107

API # : 067-09074



Photo 5: Fracturing sand. Previous inspection



Photo 6: Fracturing sand. Current inspection.

Well Name : IGE 107

API # : 067-09074



Photo 7: Thread protectors at separator.



Photo 8: High pressure hoses at wellhead.