

Photo#1:  
View North from Location Center



Photo#2:  
View South from Location Center



Photo#3:

View East from Location Center




Photo#4:

View West from Location Center



Photo#5:  
Access Road leading into Location



Photo#6:  
Erosion of Access Road



Photo#7:  
Rill Erosion on Cut Slope of Access Road



Photo#8:  
Carcass on Access Road



Photo#9:  
Lick Barrels on Location



Photo#10:  
Carcasses Littered over Location.



Photo#11:

Compacted Area where Access road enters  
Location



Photo#12:

Close up of emerging Vegetation

