

Photo#1:  
Overview of Location to South



January 18, 2018



Photo#2:

View to East over Compacted area of Location being used for vehicle access & parking at time of Inspection.



January 18, 2018



Photo#3:

Access Road Stormwater issues remain unaddressed.



January 18, 2018