

Inspected Facilities

Facility ID: 441079 Type: LAND API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

| Type | Management | Condition | GPS (Lat) | (Long) |
|-------------------|--|-----------|-----------|------------------|
| Drill Cuttings | Land Application | Adequate | | |
| Comment | No stockpiles of drill cuttings or fluids were observed. Evidence of recent drilling fluid application was present. Operator began using this location March 13, 2015 or sooner and shall cease using area by March 13, 2018. Upon final incorporation of drilling waste, Operator shall collect soil samples to demonstrate compliance with Table 910-1 and submit results to COGCC requesting closure. | | | |
| Corrective Action | Cease application of drilling waste by date stated (March 13, 2018) and submit Form 4 with closure request and documentation verifying compliance with Table 910-1 90 days thereafter (June 11, 2018). | | | Date: 03/13/2018 |

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---|---|
| 401532388 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4366644 |
| 679700807 | Krier 26-6-61 Inspection Photos 1-30-2018 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4366637 |