

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
API: 05-123-35397



Photo 1: Location, looking NW



Photo 2: Wellhead, looking N. Stained soil around wellhead.

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
API: 05-123-35397



Photo 3: Unused equipment on S side of location



Photo 4: Unused equipment, debris on S side of location

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
API: 05-123-35397



Photo 5: Unused equipment, debris, on S side of location



Photo 6: Unused equipment and debris on W side of location

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
API: 05-123-35397



Photo 7: Wellhead sign and emergency number are for prior operator



Photo 8: Stained soil at loadout.

Inspection Photos
Location Name: Black Hollow 8-67-16 #3H
API: 05-123-35397



Photo 9: Weeds in tank battery berm



Photo 10: Tanks not labeled with capacities