



Inspection Photos
Location Name: KPK Jillson #2
Location # 333238



Wellhead & Pumpjack


Tank Battery and Equipment



Oil Stains from thief hatch



Stained soil and leaks in Dog House and trash in Dog House



No labels or NFPA on tanks on Concrete Tanks

Trash on location 5 gallon bucket No labels or NFPA on Concrete Tanks