

Inspection date: Feb 09, 2018  
Ramos Yard  
Caerus Spill/Release Point ID #453964



Sign at the Entrance of the Storage Facility



View of the Storage Facility (Ramos Yard)

Inspection date: Feb 09, 2018  
Ramos Yard  
Caerus Spill/Release Point ID #453964



**Empty tank to be decommissioned**



**No fluids/sludge inside the tank**



Inspection date: Feb 09, 2018  
Ramos Yard  
Caerus Spill/Release Point ID #453964



Location where the tank was being torn down. Circular berm contained spilled sludge. There is a small stock pile on the left side of the berm.



View looking south

Inspection date: Feb 09, 2018  
Ramos Yard  
Caerus Spill/Release Point ID #453964



**Berms around the pad. Some vegetation growth observed on the berms but not on the pad.**



**Pad surface in good conditions. No staining, junk or debris observed on site.**