

# Inspection Photos

API: 05-067-09913

Operator: CATAMOUNT ENERGY PARTNERS LLC

Inspection Number: 6806024650

Inspection Date: 1/17/2018



**Photo 1. View of the project area from the northern corner facing center.**





**Photo 2. View of the western portion of the project area from the northern corner facing southwestward.**





**Photo 3. View of the northeastern portion of the project area from northern corner facing southeastward.**







**Photo 4. View of an erosional channel approximately 5.5 feet wide and deep in the northern portion of the project area. Stabilization measures are needed here.**





**Photo 5. View of another erosional channel approximately 5 feet wide and deep in the eastern portion of the project area. Stabilization measures are needed here.**





**Photo 6. View of Russian knapweed (*Acroptilon repens*) infestation along the northeastern edge of the project area.**