

Inspection Photos

API: 05-067-08749

Operator: BP AMERICA PRODUCTION COMPANY

Inspection Number: 680602487

Inspection Date: 2/5/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*), intermediate wheatgrass (*Thinopyron intermedium*), and dropseed (*Sporobolus sp.*).



Photo 3. View of the eastern edge of the working area from the northeastern corner facing southward.



Photo 4. View of the southern portion of the project area from the southwestern corner facing eastward. Portions of project area outside of fenced working area have been incorporated into surrounding irrigated pasture. Revegetation should be assessed during the growing season.