

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/20/2018

Submitted Date:

02/20/2018

Document Number:

679904036**FIELD INSPECTION FORM**
 Loc ID 320972 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10626Name of Operator: DOVER ATWOOD CORPORATIONAddress: 1875 HARSH AVENUE SECity: MASSILLON State: OH Zip: 44646**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Levengood, John	(330) 809-0630	jlevengood07@gmail.com	BACA Inspections
Crane, Rocky	719-529-0682	rockycrane@yahoo.com	Pumper (BACA)

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205623	WELL	PR	07/17/2015	GW	009-06034	COPE, NELLIE 1-16	PR

General Comment:[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt and gravel road through farm ground		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Sticker and stencil on 35bbl tank by meter shed		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Sticker on chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Sticker and stencil on water tank. NFPA label needs replaced		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	PUMP JACK		
Comment:	Wire panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:	Churchill unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:		Date:	

Type: Gas Meter Run	# 2	
Comment:	Shared meter run for Cope Nellie 1-16 and Federal 2-16X	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Electric motor	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		37.342420,-102.391370
Comment:	Fiberglass open top water tank. Tank is empty at time of inspection. Install netting if tank is to be used				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Repair and maintain berms if tank is to be used			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 205623	Type: WELL	API Number: 009-06034	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing. Casing production. Central meter run for (Cope, Nellie 1-16 & Federal 2-16X)			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT