

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401553553

Date Received:

02/23/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Inspections, All

SanJuanCOGCC@bp.com

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685304206

Inspection Date: 01/18/2018

FIR Submit Date: 01/22/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333834

Location Name: SHARP GAS UNIT-N33N10W Number: 25NENE County: LA PLATA

Qtrqtr: NENE Sec: 25 Twp: 33N Range: 10W Meridian: N

Latitude: 37.079136 Longitude: -107.878441

FACILITY - API Number: 05-067- -00 Facility ID: 215063

Facility Name: SHARP Number: 3E

Qtrqtr: NENE Sec: 25 Twp: 33N Range: 10W Meridian: N

Latitude: 37.079136 Longitude: -107.878441

CORRECTIVE ACTIONS:

1 CA# 114159

Corrective Action: Remove weeds to comply with Rule 603.f.

Date: 02/22/2018

Response: CA COMPLETED

Date of Completion: 02/06/2018

Operator Comment: Weeds and weed debris manually removed and properly disposed of. See attached photos

COGCC Decision: \_\_\_\_\_

Date: 02/22/2018

Date of Completion: 02/06/2018

Operator Comment:	Corner brace and trash cleaned up and removed from location. Debris/equipment disposed of properly see attached photos.
-------------------	---

COGCC Decision:

\_\_\_\_\_

Comment:	All CA's addressed by manual removal of weeds and debris. See attached photos
----------	---

Title: Compliance Specialist Date: 2/23/2018 9:13:16 AM

<u>Document Number</u>	<u>Description</u>
401553565	CA completion photos

Page 2 of 2