

Inspection Photos
Location Name: Bashor PC GQ #17-04
Location ID: 417833



Photo 1: Location, looking NW



Photo 2: Wellhead, looking E

Inspection Photos
Location Name: Bashor PC GQ #17-04
Location ID: 417833



Photo 3: Risers in SW corner of treater house



Photo 4: Riser S of meter run