

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2018

Submitted Date:

02/16/2018

Document Number:

689701043**FIELD INSPECTION FORM**

Loc ID 335200	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 18 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
------------------	------------------------------------	---	-------------------	---

**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252	WELL	PR	03/27/2009	GW	045-15460	N. PARACHUTE MF02B C28 696	PR
253	WELL	PR	04/17/2009	GW	045-15461	N. PARACHUTE MF01A C28 696	PR
254	WELL	PR	04/17/2009	GW	045-15462	N. PARACHUTE MF01D C28 696	PR
255	WELL	PR	04/30/2009	GW	045-15463	N. PARACHUTE MF01C C28 696	PR
256	WELL	PR	03/31/2009	GW	045-15464	N. PARACHUTE MF02A C28 696	PR
258	WELL	PR	01/31/2009	GW	045-15465	N. PARACHUTE MF02D C28 696	PR
259	WELL	PR	04/14/2009	GW	045-15466	N. PARACHUTE MF01B C28 696	PR
260	WELL	PR	01/20/2009	GW	045-15467	N. PARACHUTE MF02C C28 696	PR
291912	WELL	PR	04/14/2009	GW	045-14553	N. PARACHUTE MF15A-21 C28 69	PR
291915	WELL	PR	01/19/2009	GW	045-14552	N. PARACHUTE MF10A-21C28 696	PR
291916	WELL	PR	04/15/2009	GW	045-14551	N. PARACHUTE MF10B-21C28 696	PR
291918	WELL	PR	04/17/2009	GW	045-14550	N. PARACHUTE MF10C-21 C28 69	PR
291920	WELL	PR	04/30/2009	GW	045-14549	N. PARACHUTE MF10D-21 C28 69	PR
292039	WELL	PR	04/14/2009	GW	045-14554	N. PARACHUTE MF15B-21C28696	PR
293694	WELL	PR	04/17/2009	GW	045-15108	N. PARACHUTE MF15C-21 C28 69	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 16		corrective date
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Chemical containers at meters		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
----------	---	----------	------	---------	--------	--

PRODUCED WATER	1	<100 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)	80 bbls					
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID:	252	Type:	WELL	API Number: 045-15460 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	253	Type:	WELL	API Number: 045-15461 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	254	Type:	WELL	API Number: 045-15462 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	255	Type:	WELL	API Number: 045-15463 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	256	Type:	WELL	API Number: 045-15464 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	258	Type:	WELL	API Number: 045-15465 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	259	Type:	WELL	API Number: 045-15466 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	260	Type:	WELL	API Number: 045-15467 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing well			
Corrective Action:				Date:

Facility ID: 291912	Type: WELL	API Number: 045-14553	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291915	Type: WELL	API Number: 045-14552	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291916	Type: WELL	API Number: 045-14551	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291918	Type: WELL	API Number: 045-14550	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 291920	Type: WELL	API Number: 045-14549	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 292039	Type: WELL	API Number: 045-14554	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

Facility ID: 293694	Type: WELL	API Number: 045-15108	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401548686	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381090">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381090</a>
689701044	Inspection 689701043 photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381083">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381083</a>