

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
02/19/2018

Submitted Date:  
02/19/2018

Document Number:  
689701055

**FIELD INSPECTION FORM**

Loc ID 334745 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294325	WELL	PR	01/11/2008	GW	045-15383	SPECIALTY RESTAURANTS SG 422-26	PR
294327	WELL	PR	01/11/2008	GW	045-15384	SPECIALTY RESTAURANTS SG 322-26	PR
294328	WELL	PR	11/20/2008	GW	045-15391	SPECIALTY RESTAURANTS SG 521-26	PR
294330	WELL	PR	11/20/2008	GW	045-15392	SPECIALTY RESTAURANTS SG 421-26	PR
294341	WELL	PR	01/11/2008	GW	045-15393	SPECIALTY RESTAURANTS SG 321-26	PR
294343	WELL	PR	03/22/2009	GW	045-15394	SPECIALTY RESTAURANTS SG 431-26	WK
294344	WELL	PR	03/10/2009	GW	045-15385	SPECIALTY RESTAURANTS SG 522-26	PR
294347	WELL	PR	01/11/2008	GW	045-15386	SPECIALTY RESTAURANTS SG 531-26	PR
294349	WELL	PR	04/30/2009	GW	045-15395	SPECIALTY RESTAURANTS SG 21-26	PR
294352	WELL	PR	01/11/2008	GW	045-15396	SPECIALTY RESTAURANTS SG 331-26	PR
294353	WELL	PR	03/11/2009	GW	045-15387	SPECIALTY RESTAURANTS SG 532-26	PR
294355	WELL	PR	02/18/2009	GW	045-15397	SPECIALTY RESTAURANTS SG 31-26	PR
294356	WELL	PR	11/20/2008	GW	045-15388	SPECIALTY RESTAURANTS SG 32-26	PR
294357	WELL	PR	01/11/2008	GW	045-15398	SPECIALTY RESTAURANTS SG 22-26	PR
294358	WELL	PR	03/03/2009	GW	045-15389	SPECIALTY RESTAURANTS SG 432-26	PR
294359	WELL	PR	03/03/2009	GW	045-15390	SPECIALTY RESTAURANTS SG 332-26	PR

**General Comment:**

--

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 16		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 16		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		

Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				

**Flaring:**

Type				
Comment:				
Corrective Action:				

Inspected Facilities									
Facility ID:	294325	Type:	WELL	API Number:	045-15383	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	294327	Type:	WELL	API Number:	045-15384	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	294328	Type:	WELL	API Number:	045-15391	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	294330	Type:	WELL	API Number:	045-15392	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	294341	Type:	WELL	API Number:	045-15393	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	294343	Type:	WELL	API Number:	045-15394	Status:	PR	Insp. Status:	WK
<b>Workover</b>									
Comment:	Rocky Mountain Wireline Service swabbing unit on well.								
Corrective Action:					Date:				
Facility ID:	294344	Type:	WELL	API Number:	045-15385	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	294347	Type:	WELL	API Number:	045-15386	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								

Corrective Action:		Date:	
Facility ID: <u>294349</u> Type: <u>WELL</u> API Number: <u>045-15395</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>294352</u> Type: <u>WELL</u> API Number: <u>045-15396</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>294353</u> Type: <u>WELL</u> API Number: <u>045-15387</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>294355</u> Type: <u>WELL</u> API Number: <u>045-15397</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>294356</u> Type: <u>WELL</u> API Number: <u>045-15388</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>294357</u> Type: <u>WELL</u> API Number: <u>045-15398</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>294358</u> Type: <u>WELL</u> API Number: <u>045-15389</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID: <u>294359</u> Type: <u>WELL</u> API Number: <u>045-15390</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	Producing well		

Corrective Action:		Date:	
--------------------	--	-------	--

--

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass					
Compaction	Pass					
Berms	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401549200	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381349">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381349</a>
689701056	Inspection 689701055 photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381336">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4381336</a>