

Inspection Photos

Loc# 335010

Operator: Terra

Inspection Number: 680102702

Inspection Date: 2/22/2018



Photo#1:
View over Location to North.

February 22, 2018



Photo#2:
Erosion of Pad Surface is occurring on Southeast side of Location.

February 22, 2018



Photo#3:
Vegetation in Interim Reclamation area looks well established.

February 22, 2018



Photo#4:

What appears to be small area of Land Farming is in NW corner of Location. Annual Weeds that become debris were noted in Land Farming area and along edges of Pad perimeter.

February 22, 2018