

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2018

Submitted Date:

02/26/2018

Document Number:

679904056**FIELD INSPECTION FORM**

Loc ID 304537 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 264472 | WELL | PR | 11/17/2002 | GW | 125-08672 | M PETERSON 11-5443 | PR |

General Comment:[Routine Inspection](#)

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Trail through farm ground | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|--|
| Signs/Marker: | | | |
| Type | OTHER | | |
| Comment: | Lease sign mounted to fence at metal shed | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence at unit | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|---------------------------------------|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Metal panels around metal shed | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run in metal shed 730' W of wellhead | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator in metal shed 730' W of wellhead | | |
| Corrective Action: | | Date: | |

| | | |
|---------------------------|----------------|-------|
| Type: Pump Jack | # 1 | |
| Comment: | Jensen unit | |
| Corrective Action: | | Date: |
| Type: Ancillary equipment | # 1 | |
| Comment: | Electric panel | |
| Corrective Action: | | Date: |
| Type: Prime Mover | # 1 | |
| Comment: | Electric motor | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|----------------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | PBV FIBERGLASS | | 39.744080,-102.218440 |
| Comment: | Fiberglass water tank 50% buried 730' W of wellhead | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|---------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 210bbls |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 264472 | Type: | WELL | API Number: | 125-08672 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Meter run 730' W of wellhead by CR HH | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | Pass | Other | Pass | | | |

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT