

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/20/2018

Submitted Date:

02/20/2018

Document Number:

684905053**FIELD INSPECTION FORM**Loc ID 322888 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
,		COGCCInspections@extracti onog.com	All Inspections inc 8 North, 7 North, XPR

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449582	WELL	XX	03/10/2017		123-44382	Vetting 23	CI

General Comment:

Location Construction

Location ID: 322888 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: No traffic noted on Cherry Avenue or in front of Bella Romero School at times of inspection (2/14/18, 2/20/18). Entrance and egress point noted at Highway 34 Bus.

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 449582 Type: WELL API Number: 123-44382 Status: XX Insp. Status: CI**Complaint**Comment: [Complaint #: 200445471, 200445476](#)

Field Inspector Assigned: C Pesicka

Well Number: 05- Location #: 322888

Inspection Document #: 684905053

Nature of complaint: Traffic

If Sound GPS Coordinates of Survey Location: n/a

Inspection Observations:

Observation of Cherry Avenue and the Bella Romero School was performed on 02/14/18 and 02/20/18. At the time of inspection, no oil and gas traffic was observed on Cherry Avenue or on 20th Street in front of Bella Romero School. Entrance and egress was identified at Highway 34 BUS with tracking pad in place.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401550602	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4382811
684905054	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4382809