

## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 2/22/2018



Photo 1 – At 40.37816 -104.22974 looking south



Photo 2 - At 40.37816 -104.22974 looking southwest



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Sandy Hill Land Application Site**  
**Facility ID: 448950**  
**Inspection Date: 2/22/2018**



**Photo 3 – At 40.37816 -104.22974 looking west**



**Photo 4 - At 40.37574 / -104.23066 looking west**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Inspection Photos**  
**Location Name: Sandy Hill Land Application Site**  
**Facility ID: 448950**  
**Inspection Date: 2/22/2018**



**Photo 5 – At 40.37574 / -104.23066 looking northwest**



**Photo 6 - At 40.37574 / -104.23066 looking northeast**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 2/22/2018



Photo 7 – 40.37897 / -104.23007 looking west



Photo 8 - At 40.37897 / -104.23007 looking southwest



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Sandy Hill Land Application Site

Facility ID: 448950

Inspection Date: 2/22/2018



Photo 9 – 40.37897 / -104.23007 looking south



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources