

Inspection Photos

Loc#413761

Operator: Terra

Inspection Number: 680102700

Inspection Date: 2/22/2018





Photo#1:

View over Location from entry to North. Areas no longer needed for Use, Production, Drilling or Subsequent Operations have not been Reclaimed.

February 22, 2018



Photo#2:



Photo#3:

Unused / Unneeded Equipment noted on site.

February 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photo: Terra Loc#413761 Williams



Photo#4:



Photo#5:

Unused / Unneeded Equipment noted on site.

February 22, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photo: Terra Loc#413761 Williams



Photo#6:
Stockpiles of Material are stored at North end of Location along Cut Slope

February 22, 2018



Photo#7:



Photo#8:

Existing Berms & Slopes are Weedy and sparsely Vegetated.

February 22, 2018