

Photo#1:

Overview of B&V Slug Catcher Facility at West end of TEP Location



February 22, 2018

Photo#2:

Tank Label with incorrect Emergency Information,



February 22, 2018

Photo#3:

Gravel is needed at access road entry into Facility.



February 22, 2018