

Inspection Photos  
Location Name: Horsetail #19N-1924M-R  
Location ID: 438078



Photo 1: Location, looking NW



Photo 2: Wellhead, looking NE

Inspection Photos  
Location Name: Horsetail #19N-1924M-R  
Location ID: 438078



Photo 3: Stained soil at crude oil loadout



Photo 4: Stained soil at flowline