

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo 1: Location, looking SW



Photo 2: Wellhead

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo 3: Unused pump jack



Photo 4: Stained soil at injection pump

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo 5: Decal is for incorrect operator, has incorrect emergency number




Photo 6: Decal is for incorrect operator, has incorrect emergency number

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo 7: Stained soil at truck loadout



Photo 8: Unused risers at SE corner of tank battery

Inspection Photos
Location Name: Green #1-1
Location ID: 310566



Photo 9: Unused riser at SE corner of produced water pit