

Construction and Stormwater Inspection

February 27, 2018

Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC - #10261

Location ID: 453331

Inspection Document #: 682403340

Weld County, CO

SWSE Section 27 T7N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: G & D Hanks /27-N Pad
Location ID: 453331



Photo 1. Photo taken from the southeastern location, facing East. Operator has a Disturbance Area staked along portions of the southern location. Staff did not observe other stakes/markers to delineate for the mapped wetland shown on the Hydrology Map (Doc. #401436127).

Photo 2. Photo taken just south of the location, facing East. Canada thistle (*Cirsium arvense*), a Facultative Upland species which can occur in wetlands, was observed along portions of the mapped wetland area. Staff did not appear to observe other wetland vegetation; however, this is not the growing season for wetland vegetation, making it difficult to identify plant species.

Inspection Photos
Location Name: G & D Hanks /27-N Pad
Location ID: 453331



Photo 3. Photo taken from the southern location, facing West. Appears the Operator has further stabilized the berm BMP with equipment tracking. Operator was in-process of installing a silt fence BMP around the entire location during this inspection.



Photo 4. Photo taken from the southwestern location, facing North. Photo illustrates the Operator has installed a silt fence BMP around the western location.

Inspection Photos
Location Name: G & D Hanks /27-N Pad
Location ID: 453331



Photo 5. Photo taken from the northeastern location, facing South. See comments under Photo 4.



Photo 6. Photo taken from the northeastern location, facing West. See comments under Photo 3.

Inspection Photos

Location Name: G & D Hanks /27-N Pad

Location ID: 453331



Photo 7. Photo taken from the northeastern location, facing West. Photo illustrates the topsoil stockpile that has been salvaged and stored along the northern and a portion of the western location.

Inspection Photos

Location Name: G & D Hanks /27-N Pad

Location ID: 453331



Photo 8. Photo illustrates fugitive dust along the main access road. Operator needs to comply with Rule 805.c.