

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/23/2017

Submitted Date:

02/28/2018

Document Number:

680500166**FIELD INSPECTION FORM**

Loc ID 325531 Inspector Name: WEEMS, MARK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214955	WELL	PR	05/29/2003	OW	067-06560	M & M 1	PR

General Comment:

2017 Flowline NTO Inspection 1000' Buffer and shadowing operator pressure testing. Inspect and verify flowline test at well heads and CTB/Separator.

Inspected FacilitiesFacility ID: 214955 Type: WELL API Number: 067-06560 Status: PR Insp. Status: PR**Flowline**

#1	Type: Well Site	of Lines
----	-----------------	----------

Flowline DescriptionFlowline Type: Well Site

Size:

Material:

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure TestingWitnessed: YesTest Result: PassCharted: NoCOGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: All pressure tests ranged from 10.5-13.1 psig. All lines test okay.Corrective Action: None

Date: